

**Transport Aircraft Intrusive Inspection Project**  
**(An Analysis Of The Wire Installations Of Six Decommissioned Aircraft)**

**Final Report**

**Prepared by**

**The Intrusive Inspection Working Group**

**Christopher Smith, Chairman**

**December 29, 2000**

This report is submitted to Aging Transport Systems Rulemaking Advisory Committee (ATSRAC) in accordance with that committee's request for a joint FAA/ATA effort to complement and extend the results of the ATA/ATSRAC Non-Intrusive Inspection Project. Release of this report will be in accordance with rules established by ATSRAC.

## Executive Summary

Select wire installations<sup>1</sup> on six recently decommissioned aircraft (having four different general purpose wire types) were subject to an intensive, detailed visual inspection, followed by nondestructive testing and laboratory analysis. Results of the detailed visual inspection, nondestructive testing, and laboratory analysis were analyzed to determine the state of wire on aged aircraft as a function of wire type and service history. In addition, the results of visual inspection were compared with the nondestructive testing and laboratory analysis to determine the efficacy of visual inspection for the detection of age-related deterioration.

Nearly one thousand conditions were observed in the field with visual inspection. On-aircraft NDT and laboratory testing resulted in many additional findings on selected specimens. Most of the field-detected conditions could be classified as mis-installation or traumatic damage. There was, however, non-negligible degradation on wire, connectors, and terminals. The working group choose to focus on six important categories of wire degradation: degraded wire repairs or splices, heat damaged or burnt wire, vibration damage or chafing, cracked insulation, arcing, and insulation delamination.

It was determined that visual inspection can be effective in identifying certain conditions (heat damaged or burnt wire and vibration damage or chafing), but could probably not be relied upon to find other conditions (cracked insulation, arcing, insulation delamination, and degraded repairs or splices).

This report contains 28 specific conclusions regarding the risk associated with uncorrected degenerative conditions and recommends options for prevention or mitigation of failure. The working group recommends that these conclusions and recommendations be considered when revising best practice documentation and advisory material. The conclusions are not sufficiently specific to serve as mandatory design or maintenance requirements.

The Intrusive Inspection Working Group was responsible for execution or oversight of all activities enabling the generation this report, and its members are the primary authors.

Christopher Smith, Chairman	FAA, Airworthiness Assurance R&D (AAR 430)
Robert McGuire	FAA, Airworthiness Assurance R&D (AAR 430)
Frederick Sobeck	FAA, Flight Standards (AFS 300)
Pall Arnason	Navy, NAVAIR
David Johnson	Air Force, Air Force Research Lab
Issa Ghoreishi	Boeing Commercial Aircraft
Jean Luc Ballenghien	Airbus
Dominique Mazzarino	Airbus
Larry Stevick	Northwest Airlines
Hank Zuberer	United Airlines
Edward Block	National Air Disaster Alliance, International Aviation Safety Association
Walter Cinibulk	Raychem
Ian McLellan	Transport Canada

Many of the sections represent the work of FAA affiliates and contractors providing support to this effort, and, in some cases, these organizations authored the material of this report itself:

Roberto Mata	Sandia National Labs
Roger Clough	Sandia National Labs
Robert Bernstein	Sandia National Labs
Kenneth Gillen	Sandia National Labs

---

<sup>1</sup> “Installation” as used in this document refers to the electrical interconnect components and ancillary components such as clamps, wire ties, etc. It does not refer specifically to the process of installing wire in aircraft.

Gerry Langwell	Sandia National Labs
Rex Beach	Raytheon
Joseph Kurek	Raytheon
Armin Bruning	Lectromec
Bill Linzey	Lectromec
Noel Turner	Lectromec
Allan Ferguson	Eclipse Corp.
Kevin Steidel	Eclipse Corp.

The Working Groups efforts were supported by many adjunct members, inspectors, laboratory personnel, and advisors:

Christian Garros	Airbus	Elvin Wheeler	FAA
Tony Harbottle	Airbus	Beth Erickson	FAA
Colin Kane	Airbus	Chuck Huber	FAA
Xavier Mas	Airbus	Vi Lipski	FAA
Pascal Santi	Airbus	Stu Miller	FAA, retired
Jean Pierre Ferlier	Alcatel Cable	Glenn Hiser	FedEx
Ashok Bhattacharya	Boeing	Randy Pope	FedEx
Paul Buron	Boeing	Robert Swaim	NTSB
Cliff Pettigrew	Boeing	Lukas Zuellig	Swissair
Lonnie Williams	Boeing	John Beatty	Tensolite
Peter Bersuch	Airbus	Don Tandy	Tensolite
Joe Spielman	DHL	John Moritz	Tensolite
Lee Koegel	FAA	ATSRAC members	various
Tom Newcombe	FAA		

I, as chairman, would like to thank the Working Group for their devoted service above and beyond that which I had any right to expect. Despite the Working Group's frequent encounters and long hours in often adverse circumstances, neither the quality of work nor the morale of the group was anything less than exemplary.

The groups small size would, however, have limited the extent of the project were it not for the resources made available to it by the FAA, ATSRAC, and ATA.. This assistance came in the form of additional manpower for our inspections, advice and guidance from aviation community, and access to our subject aircraft.

## Nomenclature

ATSRAC	Aging Transport Systems Rulemaking Advisory Committee
ATA	Air Transport Association
ASTF	Aging Systems Task Force (co sponsored by the ATA and ATSRAC)
AFCB	Arc-Fault Circuit Breaker
FAA	Federal Aviation Administration
PVC	Poly-vinyl chloride
XL-ETFE	Cross-linked Ethylene-tetrafluoroethylene
XL	Cross-linked, used as prefix before polymer designation
PVDF	Poly-vinylidene fluoride
SAE	Society of Automotive Engineers
ARP	Aerospace Recommended Practice
AS	Aerospace Standard
AC	Advisory Circular
FHA	Failure Hazard Analysis
PSSA	Preliminary System Safety Analysis
FMEA	Failure Modes and Effects Analysis
NDT	Nondestructive Testing
DVI	Detailed Visual Inspection
SWAMP	Severe Wind and Moisture Problem (mil spec) or Severe Weather and Moisture Prone (Airbus)
PSU	Passenger Service Unit, aircraft appliances at each passenger seat location (e.g. reading lights)
FEP	Fluoro Ethylene Propylene

Note on trade names: This report does not use trade names to describe wire insulation. Instead we use the more generic polymer name. However, because the aviation community is more familiar with trade names, their descriptions are included below.

Kapton	Dupont, aromatic polyimide
Kynar	Elf Autochem, poly-vinylidene fluoride
Spec 44	Raychem, Crosslinked polyalkene and XL PVDF
Qaud 4	McDonnell Douglas 7484444, PVC inner layer, glass braid, with a polyamide jacket
Spec 55	Raychem, crosslinked ETFE
Stilan	Raychem, Polyarylene
Tefzel	Dupont, ETFE
Poly X	crosslinked alkane-imide (aliphatic imide)
Nylon	Dupont, polyamide

## Table of Contents

<a href="#">Executive Summary</a> .....	i
<a href="#">Nomenclature</a> .....	iii
<a href="#">Chapter 1: Introduction</a> .....	<b>Error! Bookmark not defined.</b>
<a href="#">Description of the Project</a> .....	<b>Error! Bookmark not defined.</b>
<a href="#">Description of the Data Analysis</a> .....	<b>Error! Bookmark not defined.</b>
<a href="#">Chapter 2: Aircraft Visual Inspections</a> .....	<b>Error! Bookmark not defined.</b>
<a href="#">Airbus A300</a> .....	<b>Error! Bookmark not defined.</b>
<a href="#">DC-9(1)</a> .....	<b>Error! Bookmark not defined.</b>
<a href="#">747</a> .....	<b>Error! Bookmark not defined.</b>
<a href="#">DC-9(2)</a> .....	<b>Error! Bookmark not defined.</b>
<a href="#">DC-10</a> .....	<b>Error! Bookmark not defined.</b>
<a href="#">L1011</a> .....	<b>Error! Bookmark not defined.</b>
<a href="#">Summary Results</a> .....	<b>Error! Bookmark not defined.</b>
<a href="#">Chapter 3: Non-Destructive Testing</a> .....	<b>Error! Bookmark not defined.</b>
<a href="#">Lectromec NDT Testing</a> .....	<b>Error! Bookmark not defined.</b>
<a href="#">Eclipse NDT Testing</a> .....	<b>Error! Bookmark not defined.</b>
<a href="#">Follow-on NDT Testing at AANC</a> .....	<b>Error! Bookmark not defined.</b>
<a href="#">Validation of NDT findings by Raytheon</a> .....	<b>Error! Bookmark not defined.</b>
<a href="#">Chapter 4: Laboratory Testing</a> .....	<b>Error! Bookmark not defined.</b>
<a href="#">Experimental Description</a> .....	<b>Error! Bookmark not defined.</b>
<a href="#">Overview of Experiments</a> .....	<b>Error! Bookmark not defined.</b>
<a href="#">Airbus A300</a> .....	<b>Error! Bookmark not defined.</b>
<a href="#">DC-9 (1)</a> .....	<b>Error! Bookmark not defined.</b>
<a href="#">B747-100</a> .....	<b>Error! Bookmark not defined.</b>
<a href="#">DC-9 (2)</a> .....	<b>Error! Bookmark not defined.</b>
<a href="#">L1011</a> .....	<b>Error! Bookmark not defined.</b>
<a href="#">DC-10</a> .....	<b>Error! Bookmark not defined.</b>
<a href="#">Summary</a> .....	<b>Error! Bookmark not defined.</b>
<a href="#">Chapter 5: Comparison of Inspection and Testing Results</a> .....	<b>Error! Bookmark not defined.</b>
<a href="#">Chapter 6: Analysis of Wire Degradation</a> .....	<b>Error! Bookmark not defined.</b>
<a href="#">Data Synthesis</a> .....	<b>Error! Bookmark not defined.</b>
<a href="#">Analysis of Wire Type Effects</a> .....	<b>Error! Bookmark not defined.</b>
<a href="#">RSC Analysis</a> .....	<b>Error! Bookmark not defined.</b>
<a href="#">A300 delamination</a> .....	<b>Error! Bookmark not defined.</b>
<a href="#">747 Power Feeder Chaffing</a> .....	<b>Error! Bookmark not defined.</b>
<a href="#">L1011 Switch Panel Wire Trauma</a> .....	<b>Error! Bookmark not defined.</b>
<a href="#">RSCs for McDonnell Douglas DC-9 Aircraft</a> .....	<b>Error! Bookmark not defined.</b>
<a href="#">Other Analysis</a> .....	<b>Error! Bookmark not defined.</b>
<a href="#">Chapter 7: Conclusions and Recommendations</a> .....	<b>Error! Bookmark not defined.</b>
<a href="#">Development Approach to Specific Recommendations</a> .....	<b>Error! Bookmark not defined.</b>
<a href="#">Specific Recommendations</a> .....	<b>Error! Bookmark not defined.</b>
<a href="#">General Recommendation</a> .....	<b>Error! Bookmark not defined.</b>
<a href="#">Research Recommendations of the Intrusive Inspection Working Group</a> .....	<b>Error! Bookmark not defined.</b>
<b>defined.</b>	
<a href="#">Appendix 1.1: Charter for Intrusive Inspection Working Group</a> .....	<b>Error! Bookmark not defined.</b>
<a href="#">Appendix 1.2: Transport Aircraft Intrusive Inspection Program Protocol</a> .....	<b>Error! Bookmark not defined.</b>
<a href="#">Sub-Appendix 1.2.1: Candidate Inspection Locations</a> .....	<b>Error! Bookmark not defined.</b>
<a href="#">Sub-Appendix 1.2.2: Generic Inspection Protocol</a> .....	<b>Error! Bookmark not defined.</b>
<a href="#">Sub-Appendix 1.2.3: Intrusive Inspection Flow Chart</a> .....	<b>Error! Bookmark not defined.</b>

<a href="#">Sub-Appendix 1.3.4: Visual Inspection Protocol</a> .....	Error! Bookmark not defined.
<a href="#">Sub-Appendix 1.2.5: Nondestructive Inspection Protocol – Generic</a> .....	Error! Bookmark not defined.
<a href="#">Sub-Appendix 1.2.6: Forms</a> .....	Error! Bookmark not defined.
<a href="#">Sub-Appendix 1.2.7: Wire Tests Summary</a> .....	Error! Bookmark not defined.
<a href="#">Wire Test Matrix</a> .....	Error! Bookmark not defined.
<a href="#">Appendix 1.3: Fleet Wire Type Utilization</a> .....	Error! Bookmark not defined.
<a href="#">Appendix 3.3.1: Lectromec A300 NDT Testing</a> .....	Error! Bookmark not defined.
<a href="#">Introduction:</a> .....	Error! Bookmark not defined.
<a href="#">Personnel:</a> .....	Error! Bookmark not defined.
<a href="#">Method of Test:</a> .....	Error! Bookmark not defined.
<a href="#">Results:</a> .....	Error! Bookmark not defined.
<a href="#">Appendix A: Detailed Results</a> .....	Error! Bookmark not defined.
<a href="#">Appendix 3.1.2: Lectromec 747 Testing</a> .....	Error! Bookmark not defined.
<a href="#">Introduction:</a> .....	Error! Bookmark not defined.
<a href="#">Personnel:</a> .....	Error! Bookmark not defined.
<a href="#">Method of Test:</a> .....	Error! Bookmark not defined.
<a href="#">Results:</a> .....	Error! Bookmark not defined.
<a href="#">Appendix A Detailed Results</a> .....	Error! Bookmark not defined.
<a href="#">Appendix 3.1.3 First DC-9 Testing</a> .....	Error! Bookmark not defined.
<a href="#">Introduction:</a> .....	Error! Bookmark not defined.
<a href="#">Personnel:</a> .....	Error! Bookmark not defined.
<a href="#">Method of Test:</a> .....	Error! Bookmark not defined.
<a href="#">Results:</a> .....	Error! Bookmark not defined.
<a href="#">Appendix A: Detailed Results</a> .....	Error! Bookmark not defined.
<a href="#">Appendix 3.1.4 Second DC-9 Testing</a> .....	Error! Bookmark not defined.
<a href="#">Introduction:</a> .....	Error! Bookmark not defined.
<a href="#">Personnel:</a> .....	Error! Bookmark not defined.
<a href="#">Method of Test:</a> .....	Error! Bookmark not defined.
<a href="#">Results:</a> .....	Error! Bookmark not defined.
<a href="#">Appendix A: Detailed Results</a> .....	Error! Bookmark not defined.
<a href="#">Appendix 3.1.5 Lectromec DC-10 Testing</a> .....	Error! Bookmark not defined.
<a href="#">Introduction:</a> .....	Error! Bookmark not defined.
<a href="#">Personnel:</a> .....	Error! Bookmark not defined.
<a href="#">Method of Test:</a> .....	Error! Bookmark not defined.
<a href="#">Results:</a> .....	Error! Bookmark not defined.
<a href="#">Appendix A: Detail Results</a> .....	Error! Bookmark not defined.
<a href="#">Appendix 3.1.6 Lectromec L1011 Testing</a> .....	Error! Bookmark not defined.
<a href="#">Introduction:</a> .....	Error! Bookmark not defined.
<a href="#">Personnel:</a> .....	Error! Bookmark not defined.
<a href="#">Method of Test:</a> .....	Error! Bookmark not defined.
<a href="#">Results:</a> .....	Error! Bookmark not defined.
<a href="#">Appendix A: Detailed Results</a> .....	Error! Bookmark not defined.
<a href="#">Appendix 3.1.7: Follow-Up Lectromec Testing</a> .....	Error! Bookmark not defined.
<a href="#">Introduction:</a> .....	Error! Bookmark not defined.
<a href="#">Results:</a> .....	Error! Bookmark not defined.
<a href="#">Appendix A: Detailed Results</a> .....	Error! Bookmark not defined.
<a href="#">Appendix 3.2: Eclipse Final Report</a> .....	Error! Bookmark not defined.
<a href="#">Introduction</a> .....	Error! Bookmark not defined.
<a href="#">Summary of Findings</a> .....	Error! Bookmark not defined.
<a href="#">Configuration</a> .....	Error! Bookmark not defined.
<a href="#">Conductor Integrity Tests</a> .....	Error! Bookmark not defined.

<a href="#">Insulation Resistance Tests</a> .....	<b>Error! Bookmark not defined.</b>
<a href="#">Ground circuits</a> .....	<b>Error! Bookmark not defined.</b>
<a href="#">Moisture</a> .....	<b>Error! Bookmark not defined.</b>
<a href="#">Appendix 3.3: Raytheon Validation of NDT Findings</a> .....	<b>Error! Bookmark not defined.</b>
<a href="#">Appendix 4.2.1: A Closer Look at the A300 LCL-Midspan</a> .....	<b>Error! Bookmark not defined.</b>
<a href="#">Background</a> .....	<b>Error! Bookmark not defined.</b>
<a href="#">Chemical Analysis of A300 LCL-Midspan ‘Flakes’</a> .....	<b>Error! Bookmark not defined.</b>
<a href="#">Wire Cross Section Analysis</a> .....	<b>Error! Bookmark not defined.</b>
<a href="#">Appendix 4.1.2: Supplemental Laboratory Analysis</a> .....	<b>Error! Bookmark not defined.</b>
<a href="#">DC-9 (2)</a> .....	<b>Error! Bookmark not defined.</b>
<a href="#">DC-10 Laboratory findings</a> .....	<b>Error! Bookmark not defined.</b>
<a href="#">Subappendix 4.1.2.1: DC-9 Wire Type Table</a> .....	<b>Error! Bookmark not defined.</b>
<a href="#">Appendix 4.2.1 Raytheon Test Data</a> .....	<b>Error! Bookmark not defined.</b>
<a href="#">Appendix 4.2.2: Raytheon Test Description</a> .....	<b>Error! Bookmark not defined.</b>
<a href="#">Appendix 7.1: Fault Trees</a> .....	<b>Error! Bookmark not defined.</b>
<a href="#">Degraded Repair</a> .....	<b>Error! Bookmark not defined.</b>
<a href="#">Heat Damaged or Burnt Wire</a> .....	<b>Error! Bookmark not defined.</b>
<a href="#">Vibration Damage or Chafing</a> .....	<b>Error! Bookmark not defined.</b>
<a href="#">Cracking</a> .....	<b>Error! Bookmark not defined.</b>
<a href="#">Delamination</a> .....	<b>Error! Bookmark not defined.</b>
<a href="#">Arcing</a> .....	<b>Error! Bookmark not defined.</b>

<C:\WINDOWS\Desktop\intrusive\Chapter 1.doc>

<C:\WINDOWS\Desktop\intrusive\Chapter 2.doc>

<C:\WINDOWS\Desktop\intrusive\Chapter 3.doc>

<C:\WINDOWS\Desktop\intrusive\Chapter 4.doc>

<C:\WINDOWS\Desktop\intrusive\Chapter 5.doc>

<C:\WINDOWS\Desktop\intrusive\Chapter 6.doc>



<C:\WINDOWS\Desktop\intrusive\Appendix 1.1.doc>

<C:\WINDOWS\Desktop\intrusive\Appendix 1.2.doc>

<C:\WINDOWS\Desktop\intrusive\Appendix 1.3.doc>

<C:\WINDOWS\Desktop\intrusive\Appendix 3.1.doc>

<C:\WINDOWS\Desktop\intrusive\Appendix 3.2.doc>

<C:\WINDOWS\Desktop\intrusive\Appendix 3.3.doc>

<C:\WINDOWS\Desktop\intrusive\Appendix 4.1.1.doc>

<C:\WINDOWS\Desktop\intrusive\Appendix 4.1.2.doc>

<C:\WINDOWS\Desktop\intrusive\Appendix 4.2.1.doc>

<C:\WINDOWS\Desktop\intrusive\Appendix 4.2.2.doc>

Arcing is the most severe of the conditions. Moisture is not considered in this fault tree since (by virtue of the condition itself) the potential for shorting and arcing already exists.

Sustained intermittent arcing is usually only a threat when the short-circuit current is below the circuit breaker trip threshold.

- This simplified fault tree approach is not based on FAR 25.1309.
- The fault tree does not take into account the aircraft system design, architecture, materials, which are implemented and used by aircraft manufacturers in compliance with the FAR 25.1309.
- The terms *undesirable*, *severe*, *critical* are as defined in this document. Although their definition are related to terms definitions used in SAE ARP4761, they are not identical and must not be misconstrued.