

**FLIGHT
ENGINEER
STATION**

H


**CWT REAR
SPAR CONNECTOR
FOR FQIS**


CC

G
M SHOWN
N OPPOSITE

P

K SHOWN
L OPPOSITE





28-41-11
PAGE 3

CONTINUES TO
 STA 520 TENSION TIRE FAILURE, DIVER CUT
 AT STA. 760. THAN CONTINUES TO W/B
 DISCONNECT WITH TENSION TIRE FAILURE AT
 CONNECTOR
 ONE BUNDLE HAS EVIDENCE OF ARCHING
 ON MAX AT STA. 520.

